

5 NOV 1938

by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"DIANA"

Rpt.

Bdx.

No. 5076

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to indented bottom <sup>shell</sup> plates B4 to 15 inclusive, and C3 to 12 inclusive, port side, being dealt with at the first convenient opportunity.

The Bordeaux Surveyor reports the vessel placed in dry dock, bottom cleaned and coated and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 11,38, subject as above.

100A1 )  
11,38 Bdx.) Subject etc.



Handwritten signatures and date: 12/4/38

Lloyd's Register  
Foundation

W1049-0176