

CHARLES E. ROFFEY, M.I.N.A., M.I.MAR.E.

Consulting Engineer, Naval Architect and Marine Surveyor.

Telephone Nos.:  
Office—~~4389~~ Dublin. 73889.  
Residence—63687.

9 BURGH QUAY,

DUBLIN 29th October, 1945.

The Secretary,  
Lloyd's Register of Shipping,  
71, Fenchurch Street,  
LONDON, E.C.3.

RECEIVED

31 OCT 1945

ANSD.....X.....

Dear Sir,

S.T. "ILFRACOMBE"

Inismore Strand, 21st Sept. 1945.

This vessel after stranding has been refloated with her stern frame broken as depicted in attached photograph. Have discussed repairing recommendations with Mr. Grier, and the method of repair depends on the material of construction; if of Iron Mr. Grier requires a fire weld; if of steel, electric welding will meet Classification requirements.

To ascertain nature of material I telegraphed you as per enclosure.

Yours faithfully,

*Charles E. Roffey*



© 2020

Lloyd's Register  
Foundation

W1052-0007



Referred to the Chief Ship Surveyor.

*6th No.* *R. D.*

Also for Mr. *St. Hill* to note.  
*Lewis*  
31 OCT 1945



© 2020

Lloyd's Register  
Foundation

ILFRACOMBE. London, Oct. 3. — The owners of the trawler Ilfracombe state

LL 440/145