

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

L'S NAME "ILFRACOMBE"

REPORT Mil

No. 6162

arks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

9 ("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 4th S.S. No.2 due 9,42, has been commenced by the examination of the fish hold, side bunkers, rudder and steering gear 2,43.

A further General Examination becomes due 1,46.


The class is subject to permanent repairs to set over stem and stem plating (p & s) at the Owners' convenience and to a number of shell plates and deck stringer plate etc on the starboard side abreast foremast at the first opportunity.

The MILFORD HAVEN Surveyor reports the vessel placed on slipway and bottom coated.

IT IS SUBMITTED the vessel is worthy to remain as classed with record of Docking Survey 5,45 subject as above.

5,45 Mil. Subject.

S.S. Part Held.



8.6.45.

2020

Lloyd's Register  
Foundation

W1052-0014