

# REPORT OF SURVEY FOR REPAIRS, &c.

DISCLOSED

BAY No. ....

Date of writing Report... 19... When handed in at Local Office... 19... Port of London Last Survey... 19 44

No. in Reg. Book. 27180 Survey held at on the Wood, Iron or Steel ss "Kandava" Date, First Survey... Last Survey... (No. of Visits...)

TONNAGE: GROSS 1926 UNDER DK 1326 NET 1153 Built at Sunderland By whom J. Brown Owners S.S. Co. Latvia-Belgium Line Ltd Managers Seeberg Bros. When 1901 Port belonging to Riga

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage... Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

Cell/D/Bor/D/Ba... feet; uE & B... feet; f... feet } total capacity... tons. FPT... tons; APT... tons; MT... feet. tons. } N.B.—All alterations in the existing records should be underlined.

Last Report, No. 1808 Port Rga. CHARACTER. \* for Special Survey. Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (Including date of N.B., if any). +100A1 ft. awning +LMC dk with freeboard MS 5.39 5.39 BS 7.40 ss for 370.3-5.39 TS CL 5.39 large ladders not fitted.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined. NO LATER SURVEY REPORTED Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

If so, is the report sent now, or when will it be sent?

W1054-0203

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

PRESENT CONDITION OF THE	
Decks	Bulkheads
Caulking of Decks	Ceiling
Coamings	Cement or Asphalt
Beams & Fastenings	Rudder
Outside Plating	Steering gear and its connections
" " in way of sidelights	Windlass
Frames	Have pumps been examined and found efficient?
Reverse Frames	Have Sluice Valves been examined and found efficient?
Longitudinals	Have Watertight Doors been examined and found efficient?
Transverses	Have Ventilators and their Coamings been examined and found efficient?
Floors	Air and Sounding Pipes
Keelsons	Doubling Plates under Sounding Pipes
Stringers	
Inner Bottom Plating	
Have the Tanks been examined internally?	
Have the Tanks been tested?	
Engine Room Skylights	Copper, or Y.M. (State if on Felt.) When fitted, Month Year
Coal Bunkers, Openings, Covers, &c.	Boats
Oil Bunkers	Masts, Yards, &c.
Seuppers	Condition, how ascertained (State if wedges removed.)
Cargo Hatchways	Equipment/letter
Hatches	Anchors, No. of
Planking	Cables (State if now ranged)
Caulking	" length mesh diamr. (on board.)
Treenails	" Rule length size
Breasthooks & Stemson	Chain Locker
Transoms, Pointers & Crutches	Hawsers & Warps
Timbers of Frame at openings	Standing and Running Rigging
" " at other places	Sails
Stringers, Clamps & Shelves	
Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c. :- State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 29)	Special Damage or Repair Fee (if any) (per Sec. 29)	Travelling Expenses (if chargeable)	Second Surveyor's Fee (if any)	Fees applied for,
£ : :	£ : :	£ : :	£ : :	19
				Received by me,
				19

Committee's Minute... TUES. 7 MAR 1944 Character Assigned OMIT CLASS ON RE-PRINT.



Is Certificate required? If so, to be sent to