

COPY.

22179-

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C. 3.

21st June, 1938.

Dear Sirs,

S. With reference to Greenock First Entry Report No.20581 on the Steamer "EL HIND", I have to say that it is concluded the margin plate vertical angles to tank side brackets are in accordance with the approved arrangements, but I shall be glad if you will confirm this.

I am, Dear Sirs,

Yours faithfully,

pro Secretary.

The Surveyors,
GREENOCK.



© 2020

Lloyd's Register
Foundation