

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Aingle Sc. S.S. "EL HIND" Report Grk. No. 20581**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

FIRST ENTRY.~~When due~~

*100A1

2 Dks.

Cell.DB 343' 1128t, FPT 78t, APT 47t.

FK, 7BH., pt.cem., Lloyd's A & CP.

P 37', B 146', F 33'.

O.L. 414.7'.

J. S. S.
H. S.
20.6.38

This is generally a sister ship to the "JALAKRISHNA"

The Surveyors should be ~~in~~ ⁱⁿformed ^{23/6/38} it is concluded the margin plate vertical angles to tank side brackets are in accordance with the approved arrangements, but this should be confirmed.

© 2020
The Register
Foundation