

Also what special means, in the absence of internal examination, were adopted by the Surveyor to assure himself of the thorough efficiency of those parts of each Boiler?

5c, 10, 39.

2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "NORGE" Rpt. Gen. No. 16141

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Nature of Survey COMPLETION OF SPECIAL SURVEY OF ENGINES ~~AND BOILERS~~ FOR S.S. No. 2

This Survey, due 6.39 ~~now~~ partly held 2.39 now
completed, ~~and the following repairs carried out (due to~~):-

It is submitted the vessel is eligible to remain as classed, with
notation of ~~ELMC~~ MS 2.39 as recommended.



© 2020

6.4.40

Lloyd's Register
Foundation

W1058-0191

seen, is in good condition, and the vessel is ~~eligible~~
(with date) as previously recommended.