

British

Team Turn Lovers

Belfast

1907.

Belfast

Bel. Report N° 6335.

It is submitted that the Surveyor should be requested to state whether the discharge pipes are above or below the deep water line., as this item is been omitted from Report

C. Bel 23/7

ADM
22/7/07



© 2020
Lloyd's Register
Foundation

WMO58-6198

Other closed-in spaces, if any, as follows:—

4.69

Officers Obrews place

152.5