

EXAMINED L.R. 7.41 - 12 MONTHS

18 JUN 1942

Chief Surveyors.....

Received from Chief Surveyors.....

SHIP NAME MICHAEL JEBSEN REPORT Hfx. No. 4020
Gls. 65583

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—(Extract from Sub-Committee's Report, 24/5/92.)

Survey FURTHER GEN. EXAM. due 7.42 ~~7.42~~


Indented bulwark at break of poop (p.s.)
and shell plating (p.s.a) require to be dealt with at the
first convenient opportunity.

A bower anchor and 30 fathoms of chain cable
require to be supplied at the end of the present emergency.

Insert in S.R.L:-

'Examined L.R.6.42' + 12 months
and as above.

Wals
17.6.42



(Docking date)
6.42

Lloyd's Register
Foundation

W 106-0 229