

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"MICHAEL JEBSEN"

Rpt.

H.Kg.

No.

8611

s of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This vessel was formerly classed with the Germanischer Lloyd.

The Hong Kong Surveyors now report a Boiler Survey carried out and the machinery examined under working conditions.

It is submitted the vessel is eligible for the record 'Examined 6.40-for 6 mos'.

For S.R.L:- BS 6.40.

Lloyd's Register
Foundation

1.11.40.

W106-0253