

W1060-0067

2m.11.35.

9 JUL 1941

Presented to Chief Surveyors

A. 741.

Received from Chief Surveyors

VESSEL'S NAME

S.S. Tenis de Montejurra

Report

P. 100

No. 9257

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32).)

2nd S.S. No. 2.

~~SURVEY PARTLY HELD.~~

When due

11.39.

When proposed to be completed

Reason of Survey held, &c..

The class is subject to a bower anchor and a length of chain cable being supplied.

The 2nd S.S. No. 2 became due 11.39.

The case, which is fully stated in endorsement dated 30/4/41, received further consideration on the 2nd May when the Barcelona Surveyor was informed the Committee must require definite arrangements for the Survey to be carried out without fail by the end of that month.

The Surveyor was requested to advise should the vessel not come under survey by that time, and he now cables "Owners unable to determine date for carrying out Special Survey. Letter referring this case forwarded 27th June"

The year of grace expired 11.40.

The case is submitted for the consideration of the Committee.

The Certificate of Classification to be endorsed "Cargo bulwarks not fitted" and the same notation to be printed in the Register Book

© 2020 Lloyd's Register Foundation

25
7/10
4-
180
105

7.7.41