

and the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time? Yes

10.30.

Inspected by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

11 NOV 1940 2 E

SEL'S NAME "TERGIO DE MONTEJURRA"

Rpt. Bbo. No. 9237

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Remarks of Surveyor ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 8.40 ~~now~~ ^{partly} held


now

~~completed, and the following repairs carried out (due to~~

):-

It is submitted the vessel is eligible to remain as classed, with notation of BS 9.40 as recommended.

S.S. No.2 due 11.39 - no arrangements stated.



© 2020

Lloyd's Register
Foundation

8.11.40.

W1060-0077

team
eam?
the af
ently lu
r end
bricate
of ser
ted

B.
ru
had
to
nd