

"SINT PHILIPSLAND"

Rot. 28977.

" 29034.

This Dutch vessel previously held the records of LMC 1.38, BS 3.40 and S(OG) 3.40. The vessel's class was subsequently omitted from the reprint of the Register Book.

Two reports of surveys held in 1941 have now been forwarded by the Rotterdam Surveyors. They report damage sustained through fire and afterwards being sunk.

A Special Survey was held, the screw shaft examined and the following repairs carried out. All shafting examined in lathe, cylinders rejointed, condenser tubes cleaned and refitted, water end of ballast pump renewed and funnel renewed. Combustion chamber back plate, back end of a furnace and some screw stays renewed.

An electrical installation was fitted and a First Entry report forwarded.

In accordance with the Committee's decision of 9th August 1945 regarding vessels owned in countries formerly occupied by the Germans it is submitted the vessel's class be reinstated in the Register Book with fresh records of

LMC 8.41
S(OG) 7.41

Reinstate particulars in R.B.

The vessel is reported sunk (war loss) 12.44.

11.10.45



© 2020

Lloyd's Register
Foundation

W1060-0102

main as classed with fresh records of LMC. 8-41 and notation