

2E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME "STANASFALT"

Rpt. Nwc

No. 94712

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/32.

COMPLETION-OF SPECIAL SURVEY OF ENGINES-AND-BOILERS FOR S.S. No.

This Survey, due 4,37 ~~--partly-held-at-~~ now held.

~~leted, and the following repairs carried out (due to~~

Alterations:- An additional new boiler, built under survey, has been fitted, together with an additional feed pump and feed water heater.

*fund renewed*

It is submitted the vessel is eligible to remain as classed, with fresh condition of BS 1,37, NNB(p) 1,37 as recommended.

Register Book particulars as follows:-

Delete existing boiler particulars and insert

2 SB 6 cf, HS 4415. (S)

Amend NHP to 230.



*[Signature]*  
© 3. 3. 37.

Lloyd's Register Foundation

W1060-0196

now been is in a good & efficient condition & eligible in