

2572 Appleby-Frodingham Steel Co., Ltd., Scunthorpe, Lincs.

5771

Customer North Eastern Marine Eng Co Ltd Willington Quay on Tyne Date 7/10/36
 Builder

Mark or Job No.

Customer's Order No. B 5/125/2872

Works Order No. 5/10/52

REQUIREMENTS

Briller

TENSILE—Tons per sq. inch 29/33

ELONGATION—per cent.

CONTRACTION OF AREA—per cent.

ELASTIC LIMIT—
per sq. inch or per cent.

Batch No.

Inspection Lloyds

THE UNITED
STEEL
COMPANIES LTD

We hereby certify that the material described below has been made by the Open Hearth process, and is that which has been satisfactorily tested in the presence of the Surveyor, in accordance with the rules of Lloyd's Register.

Initials of Test House Manager A.W.G.

PLATE No.	CAST MARK	POSITION	PLATE MARK	PIECES CUT	SIZE	THICK-NESS	APPROX. WEIGHT				REMARKS	
							T.	c.	qr.	lbs.		
9512	36573		2872 o/c	2	10-9 1/4	x 18	27/32		9	3	20	14
518	—		P.C	2	10-1 1/2	x 18	31/32		10	2	25	15

SURVEYOR TO LLOYD'S REGISTER

Maple

- 8 OCT 1936


GRIMSBY

LR

© 2020

Lloyd's Register Foundation

W1060-0207



© 2020

Lloyd's Register
Foundation

W1060-0207