

2572 Appleby-Frodingham Steel Co., Ltd., Scunthorpe, Lincs.

5804

Customer North Eastern Marine Eng'g Co Ltd Date 16/10/36
 Builder Willington Quay on Tyne
 Mark or Job No. Boiler 29/33
 Customer's Order No. 85/125/1872 Batch No. 2
 Works Order No. 5/10/52 Inspection Lloyd's 1


REQUIREMENTS

TENSILE—Tons per sq. inch.....
 ELONGATION—per cent.....
 CONTRACTION OF AREA—per cent.....
 ELASTIC LIMIT—
 per sq. inch or per cent.....

We hereby certify that the material described below has been made by the Open Hearth process, and is that which has been satisfactorily tested in the presence of the Surveyor, in accordance with the rules of Lloyd's Register.

Initials of Test House Manager Harley

THE UNITED
STEEL
 COMPANIES LTD

| PLATE No. | CAST MARK | POSITION | PLATE MARK | PIECES CUT | SIZE | THICKNESS | APPROX. WEIGHT | | | | REMARKS |
|--|-----------|----------|------------|------------|-----------------|-----------|----------------|----|-----|------|----------|
| | | | | | | | T. | c. | qr. | lbs. | |
| B 147 | 36732 | | 2872 | 1 | 4.11/8 x 21 1/4 | 13/8 | 3 | 2 | 18 | 16. | Re place |
| Replaces plate No A 79 Cast 36665 Shown on Mill Sheet No 8122 14/10/36 2/100  W1060-0215 | | | | | | | | | | | |

© 2020

Lloyd's Register
 Foundation