

Subject to indented shell plate E14 (P.S) being dealt with at the Owners' convenience

5

by Chief Ship Surveyor

Received from Chief Ship Surveyor 29 APR 1941

1<sup>st</sup> No. 3 SURVEY PARTLY HELD.

SHIP'S NAME

TOMISLAV

Rpt. Shi.

No. 4748

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

The 1<sup>st</sup> S.S. No. 3 due 9.40 has now been partly held as follows:-

Vessel placed in dry dock  
Bottom coated  
Hatch covers completely renewed  
and minor repairs effected

and the following repairs done (due to

) :-

It is proposed to complete the survey not stated

It is submitted ~~this proposal might be approved and the vessel be allowed to remain as classed, record of Survey and notation of S.S. being deferred until completion of same.~~

Action be deferred.

The following remains to be done to complete the 1<sup>st</sup> S.S. No. 3

is:-

A considerable part remains

29.4.41



© 2020

Lloyd's Register  
Foundation

W1061 - 0189