

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Stl. Tm. Sc. VYNER BROOKERpt. Lth No. 17329

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Longt. Transverse No. 4219Depth "d" 16.58

Framing: Table No. _____

Description Bull Augh & approved2nd Longitudinal No. 14098Proportions Length 13.65
Depth = _____Deck Sheerstrake as approved

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A1 (Stal)


1 DA (Stl, Teak S.)

Cell D.B. u.e. 19', 446. F.P.T. 716. A.P.T. 706.

FK; 6 BA. Cam. Lloyds Ar & P.

P 48'. B 76'. F 58'

In. In. S.



20-2-282020

Lloyd's Register
Foundation

W1062-0012