

THE RECEIVERS Have they been made under Survey

State No. of Report or Certificate

Is each receiver, which can be isolated, fitted with a safety valve as per Rule

Can the internal surfaces of the receivers be examined

What means are provided for cleaning their inner surfaces

Engine No. 3641 Made by Russell Newbery & Co.
~~Boiler~~

For Loch Fishing Co., Portugal

Mech. Report No. 10759

It is submitted that a copy of this Report be
forwarded to the Lisbon Surveyors for their
~~returned~~ guidance and for completion; & they be informed that
the LR certificate for the dynamo is being
retained in this office.

Date

26
19/11/61



Lloyd's Register
W1065-0124
Foundation