

(Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations)

Motor Trawlers "PORT JACKSON", "PORT LEVEN",
"PORT MADOC", "PORT NATAL", "PORTAFERRY" and
"PORTISHAM".

These vessels were built in Portugal in 1942 and
1943 for the Admiralty, The Loch Fishing Co. of Hull, Ltd.
being appointed nominal Owners.

The Modified Survey of the oil engines is due in
each case.

In reply to enquiry the Admiralty desire that the
vessels should be removed from the Register Book
and it is accordingly submitted that all particulars
should be omitted from the next reprint.

9th January, 1946.

Handwritten initials and scribbles in blue ink.

board (if assigned)
Ship and now
by whom?

ns :-

Copper, or Y.M.
(State if on
fitted, M

Yards, d

ion, how
ate if wea
ment lette

rs, No. of

(State if

length

(on

Rule leng

Locker

s & War

g and Ru

33

Sails

essel in the Register
o remain as classed



© 2019

Lloyd's Register
Foundation

W1065-0131

for Ink (MA)
not to write on

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any)	£	:	:	19