

2m, 12, 26.

at to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stl T.S. CHELSEA

Report

Gls

No. 45791

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

ure of Survey

1st Entry

When due

✱ 100A.1. (Steel) In the Yacht Register.

2 Dks (Upper 5k Leak)

D.T.f 4' 9t, D.T.a 9' 8t.

B.K 5 $\frac{1}{2}$, 4 B.H, Cam, Lloyd's A.C.P.



© 2020
Lloyd's Register
Foundation

W1066-0040

8.
12.7.26.