

Chief Ship Surveyor

Received from Chief Ship Surveyor

27 AUG 1948

S NAME

W
'LONGTON

REPORT Sou.

No. 19477

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ACTION is DEFERRED for completion of SPECIAL SURVEY (D) the greater part of which was carried out Sou. 12.47.

The SOUTHAMPTON Surveyors report the vessel placed on slipway, bottom coated, & SPECIAL SURVEY completed by examination of coal bunkers.

On account of striking quay walls, repairs effected to stem, indented stem plating (p & s), & to bridge side plating etc. (p.s.).

It is submitted the vessel is eligible to remain as classed with record of docking survey 6.48, and to have the NOTATION "S.S.Sou.- 12.47 (Dr.)" as previously recommended assigned.

6.48 Sou.

S.S.Sou.- 12.47 "(Dr.)"

J.M.B.
24.8.48

T.R.H.



© 2020

Lloyd's Register
Foundation