



LLOYD'S REGISTER OF SHIPPING,

1718 MARINE BUILDING,

VANCOUVER, B. C.,

17th MAY, 1950.

RECEIVED

22 MAY 1950

ANSD.....

*- wait Casualty
rpt.*

Secretary,
Lloyd's Register of Shipping,
London.

Dear Sir:-

T.S.S. "CHELOHSIN"

Reverting to previous correspondence regarding the
above mentioned ship, we beg to advise you that she was placed
in dry dock here last month for temporary repairs to the
aged bottom plating. This work was not carried out under
survey and the vessel was subsequently beached.

It is understood the cost of repairing the vessel
would be very high and the Owner is offering her for sale.

The ship could not operate in her present condition
in the circumstances it is submitted that a suitable Notation be
entered in the Register Book such as 'Stranded 11.49 refloated
beached 1.50'.

We shall advise you further of any developments.

We are, Dear Sir,

Yours faithfully,

For the Surveyors.



© 2020

Lloyd's Register
Foundation

W1067-0005

Referred to Mr. Perris.

Copied for Freeboard

L.R.P.

The Surveyors,
Lloyd's Register of Shipping,
1718 Marine Building,
Vancouver, B. C.

No enclosure permitted
Ne rien insérer

England.

London E. C. 3.,

71 Fenchurch Street,
Lloyd's Register of Shipping,

The Secretary,



© 2020
Lloyd's Register
Foundation

