

Er R. Bent
In Reed

Original letter with:.....

Copy of/Extract from letter received from
~~XXXXXXXX~~

ME

LLOYD'S REGISTER OF SHIPPING

1718 Marine Building,
VANCOUVER, B.C.

DRESS

reference, if any:.....

ed 17.5.50. Received 22.5.50. Answered.....

el's Name: T.S.S. "CHELOHSIN"

Dear Sir:-

Reverting to previous correspondence regarding the above mentioned ship, we beg to advise you that she was placed in dry dock here last month for temporary repairs to the damaged bottom plating. This work was not carried out under survey and the vessel was subsequently beached.

It is understood the cost of repairing the vessel would be very high and the Owner is offering her for sale.

The ship could not operate in her present condition and in the circumstances it is submitted that a suitable Notation be made in the Register Book such as "Stranded 11.49" refloated and beached 1.50."

We shall advise you further of any developments.

We are, Dear Sir,

Yours faithfully,

(Signed)

pro The Surveyors.



© 2020

Lloyd's Register
Foundation

w1067 - 0006