


826.

T. S. S. Rakuyo Maru.

4. It is concluded that no liners have been
litted to the screw shafts of this vessel
in the case of the Sinter Vessel
"Anyo Maru" but the Nagasaki Surveyors
should be requested to state whether
this is so.



© 2020

Lloyd's Register

Foundation

W1067-0112

some joints in cast iron boxes and insulated with pure rubber or rubber