

forced Thickness of cylinder liners 58.5 to 41 3/4 Are the cylinders fitted with safety valves. yes Are the exhaust pipes and
If the exhaust is led overboard near the waterline, what means are arranged to prevent water from being syph
Italy.)

LLOYD'S REGISTER AND REGISTRO ITALIANO.
FEES FOR DUAL CLASSIFICATION SURVEYS.

TRIESTE

Port Date January 17th 19 98
Name of Ship 'Virgilio', Cant. Bais N°15, S.T.T. Engines N°5106-5110
Number of Report 7818 M

Total Lloyd's Register fee 4/5 S.S. sur. conste dis 9.877.- } Lit 10.658.-
2 Rix. air. receiver... 781.- }

Total Registro Italiano fee Lit 10.902.-

Total fees Lit 21.560.-

COMBINED FEE, i.e., 5 6 (LR + RI) Lit 17.967.-

2 per cent of 5 6 (LR + RI) to be credited to Registro Italiano Lit 9.343.-

3 per cent of 5 6 (LR + RI) to be credited to Lloyd's Register Lit 8.624.-

Travelling Expenses charged (to be credited to Lloyd's Register) Lit 538

Sent to Genoa

Small Auxiliary Air Compressors, No. one No. of stages 11 Diameter 110 Stroke 110

Scavenging Air Pumps, No. none Diameter - Stroke -

© 2020

Lloyd's Register
Foundation

W1069-0130