

This trawler was sunk by collision with the

LLOYD'S REGISTER OF SHIPPING

RECEIVED
UNITED WITH THE BRITISH CORPORATION REGISTER

15 MAR 1951 Ocean Chambers, Lowgate, Hull

Telephone: 36872 (2 Lines)

Ansd. 16/3 14th March, 1951.

Steam Trawler "ST. LEANDER"


Dear Sir,

We beg to inform you that it is understood work on the attempted salvage of the above trawler, which it will be recollected was sunk in the Humber in recent months, is to be commenced about the end of the present month. We will advise you in due course as to the success or otherwise of the operation.

Yours faithfully,
The Surveyors,

Per:-

The Secretary,
LONDON.



W. Dowdell

Lloyd's Register
Foundation

W1069-0158

acquaint you that in the circumstances

operation for a short time, pending

lost ship. Tugs proceeded to their aid of the two vessels, which were in collision opposite St. Andrew's Dock. The St. Leander was holed amidships.

acked bows. It was Leander had h Company.

9. Trawler on approxi- End River. Trawler crew's Dock

Reference
Classn. &
Pubins.

PUBLICATIONS

John Reed MRP 1812



© 2020

Lloyd's Register
Foundation