

1

W.S. 99

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

Stl T.S.S. "ORONSAY"

Report

Gls

No. 44328

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry

When due _____

✦ 100 A.I. (steel) "with freeboard"

3 SKs (stl) weather dk teaks, 4th SK (stl) in fore & after holds, 5th dk in No 1 Hold.

Cell DB 533' 2311t. D.T. at sides of Engine Room & in way of tunnels 129ot

F.P.T. 116t A.P.T. 192t

F.K. ^{"BK1"} Suct Keel in way of No 2, 3, & 4 holds, 12 B.H. (Collision B.H. to weather SK)

cem, Lloyds A. CP. B 344', upper B 300', F 71'.

W107-0006

© 2019

Lloyd's Register
Foundation

29.1.25