

S.Y. "Dolaura"

Arrangement of Circuits

Circuit	8cp	32cp	Plugs	Amps	Main
1. Lower Deck Forward	17	—	—	5	$\frac{7}{8}$
2. Lower Deck Aft	30	—	—	9	$\frac{7}{16}$
3. Main Deck Forward	22	—	—	6.6	$\frac{7}{8}$
4. Main Deck Midships	42	—	2-10amp	32.6	$\frac{7}{14}$
5. Main Deck Aft	37	—	1-15 "	31	$\frac{7}{14}$
6. Shade Deck & Navigation	15	4	2-5 "	34	$\frac{7}{14}$
7. Searchlight	—	—	—	20	$\frac{7}{16}$
8. Motor Closets	—	—	—	10	$\frac{7}{16}$
9. Engines & Holds	14	—	—	5	$\frac{7}{8}$
10. Spare Way	—	—	—	—	—

WM HARVIE & Co., LTD.

ELECTRICAL ENGINEERS,

24 M'ALPINE STREET,

6.5.08 GLASGOW.

A.J.



© 2020

Lloyd's Register
Foundation

Are all the joints of cables thoroughly soldered, resin only having been used as a flux

Yes

Are all joints in