

Activity.

Dec. 1937.

J.E.

To complete the survey the safety
valves of the Donkey Boiler require to be
put in order & adjusted under steam.
This will be done at London.

It is concluded that the Greenock
Surveyor is in error in reporting that the
pump room & cargo tank suction are
connected to the main & auxiliary
bilge pumps & that these suction in fact
are connected only to pumps in
the pump room but this should be
confirmed & the Surveyor requested to
state what arrangements are made for
draining the forward hold.

Adv. Lon Surveyor re Donkey Boiler
Safety valves.

14/12/37 Please send down
to "S" after attaching
to Hall Rep.

G.P.

17/12/37

Lloyd's Register
Foundation

W1071-0056