

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel S.S. "SAMUEL DRAKE" Rpt. Lon. No. 84392.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


of Survey

Before this case receives consideration, the Surveyors should be requested to state whether the survey now carried out can be accepted as a Special Survey No. 3, & if no, whether it was considered necessary to drill the shell plating & if the plating in way of sidelights, if any, has been examined.

They should also state the spacing of forecastle beams, if the rivets in frames are spaced 7 inches or 7 diameters apart, the diameter of band pumps, & whether they are correct in reporting ^{on page 4 of report} 1 disk (steel - wood sheathed) in view of particulars given on page one.

Dr. 23.6.21

*in letter
23/6/21*



© 2020
AES
22.6.21

Lloyd's Register
Foundation

L1075-0048