

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

22nd December, 1937.

Dear Sirs,

E.


The Hong Kong & Whampoa Dock Co., Ltd.
Yard No. 782 - D.C. Shunt Wound Generators.

I have to acquaint you that the Kobe Surveyors have communicated with this Office in regard to a letter which they have received from you respecting the shunt wound dynamos for the above vessel, which, it is understood, have been ordered and received for fitting.

In this connexion I have to inform you that plans of the electrical equipment should be submitted for consideration, as required by the Rules, and as the plans for this vessel have not yet reached this Office, no details of the nature of the load are available.

Further, Certificates of Test are required to be furnished for all dynamos, and I shall be glad to receive the Certificates in this case as soon as possible. These, in addition to showing temperature rise etc., should give particulars of the voltage regulation when full load is thrown off, the field regulator remaining untouched.

I have to point out that the voltage variation on shunt wound machines is detrimental to the lamps,



© 2020
Lloyd's Register
Foundation

L1075-0117 1/2

COPY.

-2-

The Hong Kong & Whampoa
Dock Co's Yard No. 732.

causing a short life and repeated renewals, and the proposal in this instance is therefore regarded as unsatisfactory. It will, however, receive further consideration on receipt of the plans and Test Certificates.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,
HONG KONG.



© 2020

Lloyd's Register
Foundation