

Percentage of strength of circ. end seams { plate 66.0
rivets 56.3 of end.

Percentage of strength of circ. intermediate seam

s/s "Talang Akar"

Hpl 16434

The Startle pool Surveyor should be requested to forward the boiler plan, which does not appear to have been received at this office.

Lr. Hpl. 8/10/26



© 2020

Handwritten signatures and date: 8/10/26

Lloyd's Register Foundation

Mean pitch of stay tubes in nests $9\frac{1}{2}$

Pitch across wide water spaces $13\frac{1}{2} \times 7\frac{1}{2}$ Working pres

Girders to combustion chamber tops: Material Steel ✓

Tensile strength $28\frac{1}{2} / 32\frac{1}{2}$ ✓