

No. of Main Boilers 6 wtp  
See Rpt 5C. 2176  
No. of Donkey Boilers  
Steam Pressure in Main Boilers 200 Lbs  
in Donkey Boilers  
Particulars of C  
ly as  
ARACT  
Special S  
at Surve

COPY FOR LONDON OFFICE

No. 2176

# Lloyd's Register of Shipping.

The class is subject to the boilers being repaired.



Received from Chief Engineer Surveyor

Port WELLINGTON

21st December, 1936

SPECIAL SURVEY OF ENGINES AND BOILERS PARTLY COMPLETED FOR 3

## This is to Certify that I have

Surveyed the Boilers and Machinery of the STEAMER "WAHINE",  
G.R. 4436 TONS & No. 86336 IN REGISTER BOOK OF SOCIETY, FOR  
2ND SPECIAL SURVEY No. 3 WITH THE EXCEPTION OF THE PORT L. P.  
TURBINE CIRCULATING AND AIR PUMPS, ALSO COMPLETE RENEWAL OF  
B1 BOILER AND ALL PRESSURE PARTS OF A3, A4, B2, B3, & B4  
BOILERS EXCEPT STEAM DRUMS

and that I have transmitted to the Committee of Lloyd's  
Register of Shipping, London, a Report stating that all  
recommendations made by me in connection therewith have  
been carried out to my satisfaction, and that I have

Recommended that the record of REMAIN AS CLASSED WITH  
FRESH RECORD LMC11, 36 WHEN SURVEY OF ABOVE PORT L.P. TURBINE  
CIRCULATING AND AIR PUMPS IS COMPLETED

be made in the Register Book in the case of this vessel.

TO COMPLETE SURVEY - PORT L.P. TURBINE CIRCULATING AND AIR PUMPS

It is submitted the Surveyor be requested to fix  
the position of the boiler which has been entirely  
to the other boilers in the vessel. He should  
of the air receiver now fitted in connection with  
plant. It is concluded that this receiver be  
accordance with the

*George D. Lidgell*

Engineer Surveyor to Lloyd's Register.

for RB. Delete 8 WTB.  
Insert 6 WTB.

Amend MS to 20173.  
Amend NHF to 1461

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly  
executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any  
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its  
committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

© 2019 Lloyd's Register Foundation  
W1076-0135