

## Lloyd's Register of Shipping.



"MILFORD VISCOUNT -54286."



Port NOTTINGHAM. 9th June, 1947.

Ruston & Hornsby Ltd., E.5601.

O/No. 5323/T/12/450638-9.

This is to Certify that

T. D. Scott

the undersigned Surveyor to this Society did at the request of  
Messrs. Ruston & Hornsby Ltd., Lincoln,  
attend their Works on the 14th May, 1947 for the purpose of  
inspecting and testing One Size No. 2 air receivers,  
made to the order of Messrs. Ruston & Hornsby Ltd.,  
and intended for Messrs. Amos & Smith Ltd.,

The material has been tested as required by the rules, and the  
scantlings of the air receiver are in accordance with the approved plan.

Each air receiver was, in the presence of the undersigned, tested by  
hydraulic pressure to 600 lbs. per square inch and  
found satisfactory.

## PARTICULARS.

RECEIVER NUMBER.	LENGTH. Ft. Ins.	INTERNAL DIAMETER. IN.	THICKNESS. IN.	TENSILE STRENGTH. TONS PER SQ. IN.	ELONGATION. % IN.....INS.	BENDS. DEGREES.
E.5601.	4'3.5/8"	2'0.3/4"	5/16"	26/30	Capacity 11 cu.ft. Drg.No.59.B.346.	

## IDENTIFICATION MARK:—

No.	E.5601.
LLOYD'S TEST.	
	600 Lbs.
W.P.	300 Lbs.
TDS.	14.5.47.

*T.D. Scott*

Surveyor to Lloyd's Register.

Fee £ : 15 : 0.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."