



Lloyd's Register of Shipping,

Maritime Buildings, East Dock Street,

Dundee, 21st November, 1921.

Reference

S.

The Secretary,
London.

LLOYD'S REGISTER
LONDON

REC'D 23. NOV 1921

ANSD

Sir,

S. S. " ARBROATH ".

In reply to your letter of the 17th instant., regarding First Entry Report No. 8237 and Special Survey Report No. 8238 I beg to state that the stockless anchors are of an approved pattern, (Taylors). The plating in way of side lights was examined and found in good order . It was not considered necessary to drill the plating in these parts owing to its condition.

I am, Sir,

Your obedient Servant,

John H. Mackintosh



© 2020

Lloyd's Register
Foundation

W1081-0144

W1081-0144

Referred to the Chief Ship Surveyor,

Handwritten initials

22 NOV 1921

Also for Mr. S. A. Hill to note.

LOE. opened 1907
I the 1911

to its condition

was examined by the Chief Ship Surveyor and found to be in good condition and fit to receive cargo.

The cargo is in good condition and fit to receive cargo.

The cargo is in good condition and fit to receive cargo.

S. A. Hill

etc.

noted

checked

1881 NOV 22

LONDON

LOE. opened 1907

© 2020

Lloyd's Register Foundation



Handwritten text at the bottom of the page, possibly a signature or reference.