

and subsequent repairs. Repairs to the hull, masts, rigging, and other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form.

POSTPONED SURVEYS.

Name of the S.S. "HAWTHORN" No. 62177 in R.B.

Tonnage Owners

Class Port of Registry

Surveys due Special Survey due 7.50.
Boiler Survey due 9.50
The Screwshaft to be renewed by 9.50 (4 months limit)
Freeboard Certificate expired 31.12.50.

Proposed to be held

Remarks Action has been deferred in this case owing to the vessel
being laid up. In reply to enquiry the Owners state that she is
still out of commission.

Brief Surveyors' recommendations

Committee's Minute

Decision

WED. 21 MAR 1951

© 2020

Deferred
Subject

Lloyd's Register
Foundation

W1081-0250

FRI. 30 MAR 1951

Record

hand up pending
Survey

~~thx~~

Rmt

[Handwritten signature]



© 2020

Lloyd's Register
Foundation