

and subsequent repairs; and besides being detailed in the body of the report, should be summarised in the form shown below. Wherever the  
other causes; and whenever the  
management of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form.

# POSTPONED SURVEYS.

Case of the S.S. "HAWTHORN"

62177 in Reg. Bk. tons, Built

assed Owners

Port of Registry

Survey Due Special Survey due 7,50

Boiler Survey due 9,50

The screwshaft requires to be renewed by 9,50.  
(12 months limit)

In reply to enquiry the Owners state that this vessel is at present laid up and ask for permission to extend the fitting of the new screwshaft until the Special Survey is held, should this take place. The Owners add they are trying to sell the vessel and they cannot accurately forecast their arrangements until they see the position of the sale.

*Submitted action be deferred.*

*2/2  
4/9/50.*

Committee's Minute FRI. 8 SEP 1950

*Deferred*

Decision



© 2020

Lloyd's Register  
Foundation

8520-1801M

*by*