

other causes; and besides being reported the particulars should be clearly stated in the space provided on the back of this form.  
replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form.  
State also the dates and initials of any letters respecting this case.

LONDON LETTERS OF NOVEMBER, 1951  
RE SPECIAL SURVEY

fuel 5,22 etc.

action is deferred for Special Survey.

Chief Surveyors.....

Received from Chief Surveyors.....

EL'S NAME Empress of Australia REPORT Lv. No. 134389

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey Docking When due.....

Notes

Subject to sternframe (Ew 2.51 & reinforced and previously Ew) being specially examined next drydocking & to defective 17<sup>th</sup> link in stard anchor length of chain cable being dealt with by 4.52.

action is deferred for Special Survey.

Endorsement of Class (B)

Incidents in shell plating, etc. (p.s.) & (s.s.f)

Lv 3.R.L.

✓ (s.s. of Tanks every 4 years)



© 2020

Lloyd's Register Foundation

14-1-52

W1086-0072

Have ventilators and their Coamings been examined and found efficient? <u>Yes</u>	" " at other places	Chain Locker.
Inner Bottom Plating	Stringers Clamps & Shelves	Hawsers & Wires