

The class is subject to the donkey boiler not being used.

4 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

13 AUG 1952

NAME

"KAUPO"

REPORT

Rot:

No. 35012

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

IMC MS due 6.52 partly held now.

In view of the extensive repairs now recommended as a result of the present survey, the Owners have decided to sell the vessel for breaking up (see letter 14. 7. 52).

IT IS ACCORDINGLY SUBMITTED action be deferred pending further information regarding the breaking up of this vessel.



© 2020

Lloyd's Register  
11. 8. 52.  
Foundation

W108660223

Pumping arrangements to be examined