

AlgaStd. No. 22555

The Surveyor should be requested to state to what pressure the M. P. S. were tested by hydraulic pressure; also whether the blow off cocks are fitted with a spigot & brass covering plate.

© 2020

Lloyd's Register
Foundation

In Engine Room

Two 3" min. one 2 1/2" Centre.

No. and size of Suctions connec
In Holds, &c. In all ho