

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

L'S NAME "EMPIRE REST" REPORT P.Sd. No. 3758

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey ~~COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No.~~

This Survey, due 11.47 ^{now} ~~partly-~~ held ^{now-}
~~completed,~~ and the following repairs carried out (due to wear & tear):-

Some scales found in the water drums of the boiler, which it is stated was caused by leaking condenser. The condenser has now been placed in an efficient condition.

A number of defective tubes have been renewed in both boilers. Screw shaft examined and found in order.

It is submitted the vessel is eligible to remain as classed, with notation of BS 1.48, as recommended Lloyd's Register Foundation
 S 1.48, 25. 3. 48.

W1087-0022