

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

25 Ballindamm, Hamburg 1

Telegrams: Surveyors, Hamburg

Telephone: No. 33 35 39

5th March 1951

Dear Sir,

In reply to your Classing Letter of the 26th February addressed to the Kiel Surveyors respecting the motor tanker "JANKO" I have to state that the condition of class regarding the rudder post may now be deleted. It is regretted that this was not stated in the Kiel Report No. 247.

With reference to the chain cable the details are as follows:-

1 length of 15 fms. stud link chain cable 2 9/16" supplied, connected and verified. Hamburg Test Certificate 164 as follows:-

164-15 fms. 2 9/16", stamp: 4.9.50 W.A.A. 164 L.R. 116.14.0.0


2 lengths, each 15 fms. together 30 fms. stud link chain cable 2 9/16" repaired and retested by Messrs. H.C. Stuelcken Sohn, Hamburg, Test Certificate 164 as follows:-

164-30 fms. 2 9/16", stamp: 14.9.50 W.A.A. 164 L.R. 116.14.0.0.  
163.7.2.

Yours faithfully,

The Secretary,  
London.

*OC. Henry*



© 2020

Lloyd's Register  
Foundation

Without.

W1088-0125 1/2

P.T.O.

CLASSIFICATION

*He*  
*honesty*  
*12/3/51*

*See letter endorsement*

*W. B. B. 16.9.2012*



© 2020

Lloyd's Register  
Foundation