

For the information of Surveyors and the Committee only.

Received at.....

Office.....

19

Lloyd's Register of Shipping.

(Report on Vessel No. Port

No. 1020 SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~
 Castings manufactured by Messrs. Skoda Works, Ltd.
 of Pilsen C. S. R. for the Vessel No. M/3413, being built
 by Messrs. H. B. Gotawerken of Göteborg
 have been inspected by me as set forth below and found to be, so far as can
 be seen, sound and free from defects.

2 Cast Steel Propeller Brackets

rk on Forgings or Castings.

Lloyd's

No. 353

25-8-27

Prague 8th October 1927

C. P. Hughes.


	PROPELLER FRAME Brackets	BUDDER FRAME.	STEM.
Material* ...	<u>S. M. C. H. Steel</u>		
How made ...	<u>Cast</u>		
annealed ...	<u>Yes</u>		
Dimensions ...	<u>Various</u>		
Progress on Inspection ...	<u>Finished machined</u>		
Date when Inspected ...	<u>25.8.1927</u>		
CASTINGS.			
Tests on Standard Test Pieces.			
Tensile Test—			
Tens per square inch $\frac{mm}{in}$...	<u>49.4 - 47.9</u>		
Extension per cent. ...	<u>29.0 - 30.3</u>		
Cold Bending Test—			
Angle before fracture ...	<u>120° - 120°</u>		
Drop Test—			
Height from ground ...	<u>7 feet</u>		
Hammering Test—			
If made according to Rules and found satisfactory ...	<u>Yes, satisfactory.</u>		

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Fee (if any chargeable) £

To be paid at

Prague.



© 2020

Lloyd's Register
Foundation
W1088-0177

* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

n.1.28. I.