

1m.7.42.

(wreck 24 upper)  
Cook, Welton & Gemmell Ltd., Beverley.

Yard No. 708

F.E.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "BOMBARDIER" REPORT Hul. No. 52049

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 2800 Depth "d" 14.42

2nd Long. No. 8050 Proportions =  $\frac{L}{D}$  10.94

Framing Bulb angle frames as approved Sheerstrake As approved

This single screw steam trawler for the Admiralty is a sister vessel to the "GRENADIER", "LANCER", "SAPPER", "COLDSTREAMER" & "FUSILIER".


This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed +100A1 "Stm Trawler" "For Government Service"

APT 7t  
BK 8", 4BH, Lloyd's A & CP  
Q 92' F 34'  
O.L. 193.0'  
E.S.D.  
1 $\frac{5}{16}$ "

NOTE: The bottom has been coated with cement in the engine and boiler spaces, bunkers, peaks and chain locker, and Bituros enamel has been applied in the fresh water tanks. As there is no reference to the bottom having been coated in the remaining spaces, the question of laying cement in way of same will require to be considered in the event of "For Government Service" being deleted from the vessel's class.

f.c.8  
8.7.43

© 2020



Lloyd's Register  
Foundation

W1090-0173