

15c, 1.14.

1

Sent to Chief Surveyors 11.3.14.

Received from Chief Surveyors

VESSEL'S NAME *Shelss Sandra*

Report *Sh*

No. 33713

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey *1st Entry*

When due

✱ 100 A.1. (Steel)

2 Dks (Steel in Tanks)

WTB - all STB a 94 4 STB 66 f 124 647C. FRT 47C. APT 18C

FK. 5BN. Cen Llyd over. P 33, B 94 F 34

M
11.3.14



© 2021

Lloyd's Register
Foundation

W1091-0097

Burr angle, Plate, Tee bulb, or Channel
Angles on upper edge

Tie Plates