

# Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C. 3.

LLOYD'S REGISTER,  
LONDON.

7th October, 1919.

Dear Sir, RECD 8 OCT 1919  
ANSD 10/10/19  
'CRETESHADE'.

The above vessel has been brought to Shoreham, and placed on the grid for the purpose of inspecting the bottom in accordance with the Society's request (see Secretary's letter dated 27th May, 1919 to Ministry of Shipping)

The inspection of the bottom shewed the following defects in the outer skin:-

A crack about three feet long on either side of centre keelson in Holdwell: water leaking through same from holdwell. At the forward end of after hold, starboard side, a narrow strip extending from bilgeto centre keelson shews a number of voids and exposing reinforcement; also similar place on starboard side under boiler room.

Apart from these defects, the bottom appears to be in very good condition and free from voids.

Two small fractures appear in the outer skin at the port bow.

The above mentioned defects have now been made good and the bottom and sides twice coated with Wails Dove's Solution.

I am, Dear Sir,  
Yours faithfully,

*William H. Atmes*

Surveyor.

The Secretary,  
LONDON.



© 2020

Lloyd's Register  
Foundation

address  
communications  
subject to  
SECRETARY  
the following  
initial.

Dock  
Decks  
of Upper  
n, Actual  
Concrete

Referred to the Chief Surveyor,

70  
OCT - 8 - 5

for the survey to be

Noted. J.T.M.

Cf.



© 2020

Lloyd's Register  
Foundation