

COPY.

2m.10.3. n.
RCONIGRAM
BLEGRAM sent to the Surveyor at KOBE.

ted 16.3.27. H. Department.

TRANSLATION.

AFSXU

HOUTHANDEL.	- Vessel's name.
EVARO	- Vessel is due at your port
ENIRIX	- vessel has been sold to
EWIGU	- Japan
EWIGU	- S.S. N°2 must be completed on arrival at
EWIGU	- Japan
AGHUV	- the following remains to be done to
	complete S.S. N°2
	- the examination of
ENETA	- holds
AKHAK	- peaks
AKPOW	- chain locker
AWKAI	- lower
EGUHI	- bunkers
AWGHE	- engine and boiler space
AWOMA	- decks
AWLNU	- anchors
AVROM	- chain cable
AWJUL	- windlass
BANIW	- examination of steering gear
AKUNS	- examination of pumps, sluices and
AKTYB	watertight doors
	- hatches
AXCYL	- and
ECVOF	- ventilators
BAMIE	- the testing of
ENIGD	- all
ECURP	- tanks
BAFYR	- verification of freeboard
AKYFY	- no part of s.s. N°2 has been held as
AKCOV	regards engines
	- Boiler Survey is due
RECIP	- STOP.
EBTIV	- bower anchor
ANDSU	- stream chain
ANFUB	- and
ECVOF	- towline
BALIT	- require to be supplied
ELFYD	
LIVEBOATS AND MAINSTAY	- require to be renewed
ELFDU	- main topmast
AMMYW	

© 2020

Lloyd's Register
Foundation

W1096-0214 1/2

COP Y.

2.

EXFYX - to be
 REWEDGED
 STEERING GEAR BLOCKS HATCHWEB SLIDES FIDLEY
 CASING AND PIPE CASINGS
 EDDUF - in
 AWCFF -bridge
 AWGEF - bunkers
 ELMELI - require to be repaired.
 EBTIW - STOP
 EDEHU - ascertain at once and cable
 NKOSP - what arrangements have been made for
 EDUTH - completion of
 EJJYL - special survey
 ECVOF - and
 DOJUV - repairs.
 - the examination of
 - holds
 - peaks
 - chain locker
 - lower
 - bunkers
 - engine and boiler space
 - decks
 - anchors
 - chain cable
 - windlass
 - examination of steering gear
 - examination of pumps, sluices and
 watertight doors
 - hatches
 - and
 - ventilators
 - the testing of
 - all
 - tanks
 - verification of freeboard
 - no part of s.s. N°2 has been held as
 regards engines
 - Boiler Survey is due
 - STOP.
 - bower anchor
 - stream chain
 - and
 - towline
 - require to be supplied
 LIFEGRAPE AND MAINSTAY
 - require to be renewed
 - main topmast



© 2020

Lloyd's Register
Foundation

W1096-0214 1/2

W1096-0215 1/2

096-0215 2