





It was stated that these recommendations would be carried out at Antwerp & the remainder of the survey carried out at Kobe & an appointment was made with the Superintendent to see the repairs completed today 17th/11/26. He however telephoned stating that the vessel sailed last night. It is understood that the Starboard life boat has been renewed, but this has not been verified.

Nothing done now in connection with Brayley Survey.

J. O. Hubert

## ANCHORS.

Number of Certificate.	Anchors.*	WEIGHT, EX. STOCK.			WEIGHT OF STOCK.			TEST, PER CERTIFICATE.				WEIGHT REQUIRED BY RULE.			Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.	Tons.	Cwts.	qrs.	lbs.	Cwts.	qrs.	lbs.			
	1st Bower																
	2nd "																
	3rd "																
	Collective Weight.																
	Stream																
	Kedge																

\*If Patent Trade name of Patentee.  
 \*Stockless, State Mechanical Tests

\* When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

## CHAIN CABLES.

[illegible]

Iron Stream Chain )  
or Steel Wire... )

Even

Know

mon

decis

**23.—**If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

General Committee  
Thursday, 21<sup>st</sup> March, 1927.  
Closing Committee's

Iron Stream Chain }  
or Steel Wire... }

© 2020

Lloyd's Register  
Foundation