

Received by Chief Ship Surveyor *2/1/08*

Received from Chief Ship Surveyor

VESSEL'S NAME *St. S. Trawler "Coltman"* Rpt. *Steel* No. *19681*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>10" in lieu of 7"</i>	<i>not required</i>
Spar Sheerstrake . .	<i>✓</i>	<i>✓</i>
Description of Framing:— <i>Ordinary, increased to compensate for (viz., ordinary, deep, zed, channel or bulb-angle) omission of some frames.</i>		

The chain cables are not 2 qrs 23 lbs or 18 of 1 1/2 lbs in weight than required by Table 22. The Owners state they are willing to accept the cables (as per letter attached).

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+100A1 (Steel) "Steam Trawler" as recommended.*

+100A1 (Steel) "Steam Trawler"

10"

B.K. 8" H.B.H. Cam. Lloyds A & C Q72 F23

RBT

C.H. 1
2/1/08
© 2021
Lloyd's Register
Foundation